

APPENDIX -L
FORM 'S'
[SEE RULE 88 (5)]
Fire Audit Report
Year 2023

To

1. The Director

Vatsalya Public School, Dist. Mandsaur , Madhya Pradesh

Sir,


Sub: Submission of fire audit report of Vatsalya Public School and Address Vatsalya Public School Yash Nagar Mandsaur , Dist. Mandsaur , Madhya Pradesh.

I **Shobhit Bansal**, have inspected your building / premises on **7 March 2023** with Vatsal Public School Authorised Team and checked all Fire Equipments / installations and have completed the Fire Audit of the said building / premises of Address **Vatsalya Public School Yash Nagar Mandsaur Madhya Pradesh**.

2. Detail of fire system installed are as below :-

S.No.	Particular	Available/Installed or not installed (as per requirements) (give comments)	Comments for working of System (attach details, if needed)
1.	Access	Available	Multiple way to Entry & Exit
2.	Wet Riser	Not Available	Not Required As per NBC Part-4
3.	Down Comer	Not Available	Not Required As per NBC Part-4
4.	Hose reel	Not Available	Required
5.	Automatic Sprinkler System	Not Available	Not Required As per NBC Part-4
6.	Yard Hydrant	Not Available	Not Required As per NBC Part-4
7.	Underground tank with Draw of connection	Not Available	Not Required As per NBC Part-4
8.	Terrace Tank	Available (15000 ltr)	Sufficient


Principal
Vatsalya Public School
Mandsaur


Shobhit Bansal
Fire Engineer/Authorised Consultant
Nagar Palika Parishad, Mandsaur (M.P.)

9.	Fire Pump	Not Available	Not Required As per NBC Part-4
10.	Terrace Pump	Not Available	Not Required As per NBC Part-4
11.	First Aid Fire Fighting Appliances	Available	ABC Type – 6kg – 01 ABC Type – 4kg – 14 ABC Type – 2kg – 08 ABC Type – 1kg – 03 ABC Type – 500gm- 02
12.	Pressurization System	Not Available	Not Required As per NBC Part-4
13.	Auto detection System	Not Available	Not Required As per NBC Part-4
14.	Manual Operated Electrical Fire Alarm System	Available	Maintain
15.	P.A System with talk back facility	Available	But talk back facility not Available
16.	Emergency Light	Not Available	
17.	Auto D.G. Set	Not Available	
18.	Illuminated Exit Sign	Available	
19.	Means of Escape	Available	Available
20.	Compartmentation	Not Available	Not Required As per NBC Part-4
21.	MCB/ELCB	Installed	Maintain
22.	Fireman Switch in Lift	Not Available	Not Required As per NBC Part-4
23.	Hose Boxes with Delivery hose and Branches	Not Available	Not Required As per NBC Part-4
24.	Refuge Area	Not Available	Not Required As per NBC Part-4
25.	Any other installation	No	No

It is certified that the building is inspected as per NBC part-4 according to table-7 is given above are the observations.

Date : 7 March 2023


Name of Fire Engineer : Shobhit Bansal

Designation : Fire Consultant

Department : Nagar Palika Parishad, Mandasaur, (M.P.)

License No. : 1/202/12.09.22

Signature :


Shobhit Bansal
 Fire Engineer/Authorised Consultant
 Nagar Palika Parishad, Mandasaur (M.P.)


Principal
 Vatsalya Public School
 Mandasaur